



Wind Things Up With Reelcraft

Tech Bulletin

Hand Crank to 4A & 6A Air Motors Requirements

S600767

C 33112 L TO A 33112 L4A	
QTY	PART NO. & DESCRIPTION
1	260428 Drive Motor
1	260405 Motor Bracket
1	260406 Drive Chain
1	260407 Spool Gear
1	260436 Motor Gear
3	300039 Washer
3	S2-42 Hex Head Screw
4	S2-52 Hex Cap Screw
4	300107 Lock Nut
6	S27-112 Flat Cap Socket Screw
6	S79-3 Flange Nut
6	260410 Gear Spacer
1	C4546 Carton
1	261376 Shipping Bag

S600770

C 33112 L TO A 33112 L6A	
QTY	PART NO. & DESCRIPTION
1	260429 Drive Motor
1	260433 Motor Bracket
1	260406 Drive Chain
1	260407 Spool Gear
1	260408 Motor Gear
3	300039 Washer
3	S2-51 Hex Cap Screw
4	S2-52 Hex Cap Screw
4	300107 Lock Nut
6	S27-112 Flat Cap Socket Screw
6	S79-3 Flange Nut
6	260410 Gear Spacer
1	260464 Carton
1	261376 Shipping Bag

S600787

C412115 L TO A412115 L6A	
QTY	PART NO. & DESCRIPTION
1	260429 Drive Motor
1	260613 Motor Bracket
1	260582 Drive Chain
1	260566 Spool Gear
1	260365 Motor Gear
3	S10-57 Hex Cap Screw
4	S2-51 Hex Cap Screw
4	300107 Lock Nut
8	300043 Machine Screw
8	S281-4 Hex Flange Nut
8	260579 Gear Spacer
1	C4544 Carton
1	261376 Shipping Bag