



*Wind Things Up With Reelcraft*

## **Tech Bulletin**

# **Hand Crank to Explosion Proof Motors Requirements**

S600781

C 33112 L TO E 33112 L10AX	
QTY	PART NO. & DESCRIPTION
1	260430 Drive Motor
1	260456 Spacer
1	260406 Drive Chain
1	260407 Spool Gear
1	260434 Motor Gear
4	300039 Washer
4	S2-52 Hex Cap Screw
4	S44-3 Machine Screw
6	S27-112 Flat Cap Socket Screw
6	S79-3 Flange Nut
6	260410 Gear Spacer
1	C4546 Carton
1	261376 Shipping Bag

S600782

C 33112 L TO E 33112 L12DX	
QTY	PART NO. & DESCRIPTION
1	260583 Drive Motor
1	260456 Spacer
1	260406 Drive Chain
1	260407 Spool Gear
1	2604343 Motor Gear
4	300039 Washer
4	S2-52 Hex Cap Screw
4	S44-3 Machine Screw
6	S27-112 Flat Cap Socket Screw
6	S79-3 Flange Nut
6	260410 Gear Spacer
1	C4546 Carton
1	261376 Shipping Bag

S600783

C 33112 L TO E 33112 L24DX	
QTY	PART NO. & DESCRIPTION
1	260626 Drive Motor
1	260456 Spacer
1	260406 Drive Chain
1	260407 Spool Gear
1	260434 Motor Gear
4	300039 Washer
4	S2-52 Hex Cap Screw
4	S44-3 Machine Screw
6	S27-112 Flat Cap Socket Screw
6	S79-3 Flange Nut
6	260410 Gear Spacer
1	C4546 Carton
1	261376 Shipping Bag